Replace ATF Cooler Cleaner Filters Once a Year

Currently Applies To: ALL Vehicles

The two spin-on filters for the ATF Cooler Cleaner (P/N GHTTCF6H) should be replaced once a year or after you've cleaned about 100 ATF coolers. Don't use an ordinary automotive oil filter as a replacement. The actual replacement filter has magnets to trap metallic particles. It also doesn't have an internal bypass valve.

You can order replacement filters by calling the Honda Tool and Equipment Program at **888-424-6857**. Here's the ordering info:

G-TEC Filter (2-pack):
P/N GTHGNBP2

G-TEC Filter (6-pack):
P/N GTHNBP2

G-TEC Filter (12-pack):
P/N GTHNBP12

You can also order online through the iN. From the main menu, click on **SERVICE**. You can then click on either **Service Bay** and **Tool and Equipment Program** or **eMall** and **Tool & Equipment**. Either way takes you to the Tool and Equipment Program webpage. Once there, click on **Online Catalog**, enter the part number in the **Search** box, and click on **Go!**. You're taken straight to the order page.

© 2007 American Honda Motor Co., Inc. – All Rights Reserved